

## RFI – GAUL – Underwater Survey 2002

### Daily Report No 6

#### On board *SEISRANGER*

Date:	01.07.02	Time:	2359	Day No. (On Site):	1
Location:	N 72° 04.1' E 025° 05.3' (on wreck site)				
Weather: (past 24 hours)	Fair/good visibility	Sea State:	3	Wind Speed & Direction:	10 knots ENE
Weather: (next 3-5 days)	E'ly 10kts veering S 20kts & then SW'ly 5 kts.				

#### Summary:

Arrived on site at 0610, first ROV in water at 0705 and wreck located at 0848. Very good quality pictures returning to the survey vessel from the ROV.

#### Progress over the last 24 hours:

- Wreck positively identified at 0853
- Dynamic positioning equipment calibrated
- Ultra short base line calibrated
- Preliminary external examination of the wreck and nets
- Side scan sonar survey started

Survey planning meeting and debrief completed.

The attached chartlet shows progress to the wreck site.

#### Plan for the next 24 hours:

- Complete side scan survey
- Seabat survey of areas of special interest.
- Track seabed cables and obtain samples.
- Onboard work on the funnel tool.
- Photomosaic of wreck.

Keith Dixon  
Team Leader