

## RFI – GAUL – Underwater Survey 2002

### Daily Report No 11

#### On board *SEISRANGER*

Date:	06.07.02	Time:	2359	Day No. (On Site):	6
Location:	N 72° 04.1' E 025° 05.3' (on wreck site)				
Weather: (past 24 hours)	Poor visibility	Sea State:	3	Wind Speed & Direction:	10-15 knots E'ly
Weather: (next 3-5 days)	E'ly 5-10kts backing NW'ly 10-15kts & veering E'ly 8-10kts.				

#### Summary:

Progress has been made in cleaning and examining external items. Photogrammetry of the outboard side of the port funnel and bow damages is complete.

#### Progress over the last 24 hours:

- Nets removed completely from aft quarter to allow access to trawl deck and trawl wires.
- Analysis of side scan sonar and seabat data continuing.
- Photogrammetry of the funnel and bow distortion complete.
- External cleaning and visual survey continues.

Survey planning meeting and debrief completed.

Image shows the ROV leaving the TMS near the wreck, and the ROV lights shining through one of the many shoals of fish.

#### Plan for the next 24 hours:

- Manage and remove more nets.
- Complete photogrammetry of kort nozzle and controllable pitch propeller.
- Photomosaic over the top of the wreck.
- Complete external cleaning and visual survey.

Keith Dixon  
Team Leader