

## RFI – GAUL – Underwater Survey 2002

### Daily Report No 4

#### On board *SEISRANGER*

Date:	29.06.02	Time:	2359	Day No. (On Site):	n/a
Location:	N 68° 02' E 012° 45'				
Weather: (past 24 hours)	Fair/good visibility	Sea State:	4/5	Wind Speed & Direction:	15 knots NW
Weather: (next 3-5 days)	Expected weather on site 01/06/02 NE force 2-3				

#### Summary:

Sea conditions moderated and good progress today at 12 knots. ETA on wreck site is now morning of 1<sup>st</sup> July 2002.

325 n miles to wreck site.

#### Progress over the last 24 hours:

Meetings on board to plan the first four phases of the wreck survey.  
Subsea 7 ROV teams are viewing the 1998 underwater survey video recordings.

The attached image shows the work class ROV configured with specialised equipment for the first deployment on wreck site.

The attached chartlet shows progress so far and current position.

#### Plan for the next 24 hours:

Continue en-route to wreck site.

Continuation of on board meetings.

Keith Dixon  
Team Leader