

RFI – GAUL – Underwater Survey 2002

Daily Report No 5

On board *SEISRANGER*

Date:	30.06.02	Time:	2359	Day No. (On Site):	n/a
Location:	N 71° 11' E 021° 40' (off Soroya Island)				
Weather: (past 24 hours)	Fair/good visibility	Sea State:	5	Wind Speed & Direction:	20 knots NNE
Weather: (next 3-5 days)	Expected weather on site 01/07/02 ENE force 4				

Summary:

Today the vessel has made about 12 knots in sea state 5. The ETA on wreck site is morning of 1st July 2002.

Progress over the last 24 hours:

Meetings on board to plan in detail the first four phases of the wreck survey.

The attached chartlet shows progress so far and current position.

Plan for the next 24 hours:

Continue en-route to wreck site. Once on the site carry out the following tasks:

- Trial on the ship's dynamic positioning equipment
- Sonar beacon to be placed on seabed and survey systems to be calibrated.
- ROV to determine the wreck's position accurately, and examine the site for nets.
- Side scan sonar plot of the seabed surround the wreck

Keith Dixon
Team Leader