

RFI – GAUL – Underwater Survey 2002

Daily Report No 27

On board *SEISRANGER*

Date:	22.07.02	Time:	2359	Day No. (On Site):	22
Location:	N 72° 04.1' E 025° 05.3' (on wreck site)				
Weather: (past 24 hours)	Good visibility	Sea State:	3	Wind Speed & Direction:	8 knots NW'ly
Weather: (next 3-5 days)	NE'ly 10knts. becoming ESE'ly 22knts.				

Summary:

The survey has been further extended until Wednesday midnight to provide a better chance of achieving all of the survey objectives.

Work continues around the clock, using grit and disc cutting methods.

Progress over the last 24 hours:

- Work has continued to widen the holes in the side of the wreck to allow the retrieval of items of interest.

Plan for the next 24 hours:

- To retrieve items of interest for forensic examination.

Keith Dixon
Team Leader