

RFI – GAUL – Underwater Survey 2002

Daily Report No 28

On board *SEISRANGER*

Date:	23.07.02	Time:	2359	Day No. (On Site):	23
Location:	N 72° 04.1' E 025° 05.3' (on wreck site)				
Weather: (past 24 hours)	Good visibility	Sea State:	3	Wind Speed & Direction:	15 knots E'ly
Weather: (tomorrow)	ESE'ly 21-23knts.				

Summary:

The survey has only 24 hour until completion and work continues around the clock to achieve the final survey objectives.

The image shows this work in progress. ROV engaged in searching the accommodation areas through one of the grit cut holes in the side of the wreck.

Progress over the last 24 hours:

- Work has continued to widen the holes in the side of the wreck to allow the retrieval of items of interest.

Plan for the next 24 hours:

- To retrieve items of interest for forensic examination.

Keith Dixon
Team Leader